

GT SCADA - Software de Supervisión CDG030

Este software de supervisión CDG030 permite supervisar, en tiempo real, un parque de equipos Gorgy Timing. Asegura la supervisión estadística de las características de la instalación vía SNMP. Proporciona trazabilidad de las anomalías en ficheros logs. Software compatible con: Windows® XP / 2003 / Vista (32 bits) / Windows 7 / Windows 8.

The image displays three main windows from the GTSCADA software:

- GTSCADA Supervision V2.08:** A dashboard showing the status of various devices. Each device is represented by a green checkmark icon (indicating normal operation) or a red 'X' icon (indicating an issue). The devices listed include IP addresses from 192.168.1.4 to 192.168.1.156.
- GTSCADA Analyze:** A window for analyzing specific device data. It shows a table with columns for IP Address, Model, and MAC Address. A pie chart titled 'Pourcentage' displays the distribution of states. Below the chart, there are date and time filters and an 'Export Excel' button.
- GTSCADA Supervision V2.08 (Detailed View):** A table showing a detailed log of device states and events. The table includes columns for IP Address, Model, State, MAC Address, and Trap's Number.

IP Address	Model	State	MAC Address	Trap's Number
192.168.1.4	LEDI NET TOTAL IEC	Normal behaviour, current clock is locked on remote server clocks, outpu...	00:40:9D:6C:EE:8C	In Active Mode
192.168.10.45	LEDI Network ITS SNMP_2.1	Power supply has returned	00:40:9D:32:C7:FF	In Active Mode
192.168.10.82	LEDI Network ITS v2	Input 1 is synch again	00:40:9D:6F:7E:EA	In Active Mode
192.168.10.107	GT RT9s 140685 proto	The device is synchronized on its external source	00:40:9D:71:1C:01	In Active Mode
192.168.10.110	LEDI Network ITS v2	Input 2 is unsynch	00:40:9D:6F:A3:A1	In Active Mode
192.168.10.136	GT RT9s 140686	The device is synchronized on its external source	00:40:9D:6C:EE:A4	In Active Mode
192.168.10.144	GT RT9s 123061	User forced the internal Clock as a time synchronization source	00:40:9D:4E:82:4E	In Active Mode
192.168.10.151	LEDI Network ITS v2	The device has never been externally synchronized by a time source	00:40:9D:68:98:2B	In Active Mode
192.168.10.174	LEDI Network ITS v2	NTP server software is rescaled on PPS	00:40:9D:6F:7E:E1	In Active Mode
192.168.10.202	LEDI Network ITS SNMP_2.1	The device is now externally synchronized	00:40:9D:50:76:E8	In Active Mode
192.168.1.56	LEDI NET 144304	Normal behaviour, current clock is locked on remote server clocks, outpu...	00:40:9D:77:95:6E	In Active Mode

REFERENCIA

VERSIÓN

Windows® XP / 2003 / Vista (32 bits) / Windows 7 / Windows 8 en versión Inglés, Francés o chino

C D G 0 3 0

